

Ph: 02 6239 5656 fax: 02 6239 5669 email: admin@robsonenviro.com.au 140 Gladstone Street, Fyshwick ACT 2609 PO Box 112, Fyshwick ACT 2609 <u>www.robsonenviro.com.au</u> ABN 55 008 660 900

Peter Folkard ACT Property Group PO Box 777 Fyshwick ACT 2609

14 May 2014

Re: Cleaning Procedures for Window Glass with Asbestos Containing Putty

Dear Peter,

Windows that have asbestos putty used as a sealant which contain asbestos presents a negligible risk if not disturbed. Concerns have been raised in the past that where large hardened and brittle fragments of asbestos containing window putty become dislodged through weathering, the risk of exposure increases if a child were to abraid the fragment against a masonry surface. The perception is that during this abrasion process the asbestos within the putty may become airborne and potentially be inhaled by students.

Robson Environmental has been supplied with a Glass Cleaning Procedure provided by a ACT Property Group approved window cleaner.

The document addresses the following items with respect to glass cleaning;

- Purpose,
- Materials used,
- Procedure for cleaning the Glass
- Safety &
- Care of equipment.

The Procedure should also note that all glass cleaning staff are Working at Heights Trained and Asbestos Awareness Trained. It is also strongly recommended that a First-Aid Trained staff member is on the particular cleaning team and that personnel do not work alone.

The window cleaning staff should adhere to the following dot points when preparing to and cleaning windows;

- Check with the asbestos management plan located at the reception to determine whether the window putty contains asbestos.
- Where asbestos putty exists the window cleaners must avoid damaging the putty. The soft squeegee's and dry cloth used on the windows are highly unlikely increase the risk of exposure. The scraping of windows to remove paint spots or tape spots may damage the asbestos putty if not undertaken with care.



Window Cleaning Procedures

- If damage occurs or the condition of the putty has weathered sufficiently for fragments of the asbestos putty to become dislodged, the cleaners should isolate the area with signage or barricades and cover the putty fragment with plastic. If they are Asbestos Awareness Trained the cleaners should double bag the asbestos debris and place in a sealed container. In either case a licensed ACT Asbestos Removalist must be contacted to collect and dispose of the waste and remediate the areas of putty in poor condition.
- In the circumstance where cleaners identify windows where the asbestos putty is loose or dislodged the windows must remain uncleaned until the areas are remediated by a licensed ACT Asbestos Removalist.
- Lines of communication should be set up between the Cleaning Contractors and an ACT Property Group representative, to respond as soon as practicable should either of the above two items eventuates.

Robson Environmental



Adam Dezman ACT Property Group PO Box 777 FYSHWICK ACT 2609

27 May 2014

Dear Adam,

Re: Asbestos analysis and risk assessment of 2 samples collected from the Yarralumla Primary School – 14 January 2015

Site Work

, Class A Asbestos Assessor of Robson Environmental sampled suspected asbestos containing material (ACM) from the above location, as shown on the attached figure. Analytical results for sampled material are presented in Table 1.

Risk Assessment

A Risk Assessment was undertaken on all asbestos containing materials (ACM) to enable informed decisions to be made concerning the management of ACM as per NOHSC: 2018 (2005). This Risk Assessment takes into account:

- the type of ACM (bonded or friable)
- the condition and location of the ACM
- whether the ACM is likely to be disturbed due to its condition and location and
- the likelihood of exposure to asbestos fibre

Material Assessment Restrictions and Caveats

Robson Environmental has taken care to ensure that this report includes the most accurate information available. This report does not constitute a full register of asbestos containing materials at the above establishment as required by State Legislation and the National Code of Practice. The material assessments, recommendations and/or conclusions contained in this report must not be used to excuse a person of their responsibility to work in accordance with relevant Statutory Requirements, Codes of Practice, Guidelines, Material Safety Data Sheets, Work Instructions or reasonable work practices.

Table 1 details the ratings for the condition and associated risk of each positively identified asbestos material at the time of the assessment. The ratings for each item are presented in Table 2.



Table 1: ACM Condition & Risk Ratings

	ACM CONDITION RATING				
1	Severe	Material in very poor condition			
2	Poor	Deteriorated material and considerable damage			
3	Fair	Minor damage			
4	4 Good Well sealed stable material				
	ACM RISK RATING				
Α	Very High	Exposure to airborne asbestos likely as a consequence of minor disturbance			
В	High	Exposure to airborne asbestos possible as a consequence of minor disturbance			
С	Medium	Exposure to airborne asbestos unlikely during normal building use			
D	Low	Negligible exposure to airborne asbestos during normal building use			

LABORATORY METHODOLOGY

Sampled material was double bagged and transported to the Robson Environmental's National Association of Testing Authorities (NATA) accredited laboratory. Samples were delivered with a Chain of Custody (COC) form written by the assessor which was signed off on receipt by the laboratory. The received materials were analysed for asbestos fibre content which is determined by Polarised Light Microscopy with dispersion staining techniques. The certificate of analysis and COC are presented in Appendix B.

The samples taken from suspected ACM are representative of the materials sampled, individually identified, transported, analysed and reported in accordance with the Commission NOHSC Guidelines, relevant Statutory Regulations, Codes of Practice and Robson Environmental In-house Procedures 2 & 3.

All inspections, sampling, identification and reporting was undertaken in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations.

Bonded ACM

Bonded asbestos is any material that contains asbestos firmly bound into a matrix. It may consist of cement or various resins/binders and cannot be reduced to a dust by hand pressure. As such it does not present an exposure hazard unless cut, abraded, sanded or otherwise disturbed. Therefore, the exposure risk from bonded ACM is negligible during normal building occupation.



Note: If bonded ACM is damaged or otherwise deteriorated, the Risk Assessment must be reviewed to reflect a higher potential for exposure to asbestos fibres. When severely damaged, bonded ACM must be assessed as being friable. A Class A Asbestos Assessor must perform the Risk Assessment.

Friable ACM

Friable asbestos material can be crumbled or reduced to a dust by hand pressure when dry. It can represent a significant exposure hazard as a consequence of minor disturbance. Examples of friable asbestos are hot water pipe lagging, severely damaged asbestos cement sheet, limpet spray to structural beams and electrical duct heater millboard.

Table 2: Sample Analysis Results

Sample Number	Location description	Material	Туре	Risk Rating	Fibrous Content
D1512	After school care – external window	Mastic	-	-	No asbestos detected
D1513	Preschool	Mastic	-	-	No asbestos detected

Asbestos containing material		
Presumed asbestos containing material		
Non- asbestos containing material		

Conclusions & Recommendations

No asbestos was detected in any of the samples, therefore no action is required.

Yours sincerely,





Material Analysis & Assessment

APPENDIX B - FIBRE IDENTIFICATION CERTIFICATE OF ANALYSIS

Robson ENVIRONMEN Effective Environmental Se	NTAL olutions	140 Gladstone Street Fyshwick ACT 2609 P: 02 6239 5656 F:02 6239 5669 E: fibreid@robsonenviro.com.au W: www.robsonenviro.com.au
Fibre Ide	ntificatio	n Certificate of Analysis
Report Number: 7335471	Date of Report: 16.01.20	015 Samples Taken by: Robson Environmental Page 1 of 1
Client Details		Laboratory Details
Client: ACT Property Group		Address: 140 Gladstone Street, Fyshwick, Canberra 2609
Attention: Adam Dezman		Manager:
Received: 14.01.2015		Telephone: 02 6239 5656
Client Reference: Yarralumla P	rimary School	Fax: 02 6239 5669
Email: N/A		Email: hazmat@robsonenviro.com
Test Specification(s) Employed	+ AS4964 (2004) & In-Hous	se Procedure No 2
Poor opposition and in (o) Employed	Methoda	alogy Summary
allow unequivocal identification of asb positive identification of fibrous asbesto	pestos types, and so, to determine os is not possible.	resultorm of not. Cateria application of the test procedure provides sumclear diagnostic clues to a whether a sample contains asbestos or not. If sufficient diagnostic clues are absent, then
Robson Environmental is not responsi samples delivered to the laboratory are interpretation of the results shown. Wh for sampling. Robson Environmental ta	ble for the accuracy or competence a given by the client at the time of d nen the test certificate indicates that akes responsibility of information re	u p p t t e d S a m p t e s e of sampling carried by third parties. Sample location(s) and/or sample type(s) of third party felivery. Under these circumstances, Robson Environmental cannot be held responsible for the t bulk samples were taken by the client, they are outside the scope of our NATA Accreditation ported only when a staff member takes the sample(s).
'Ashestos Detected': Ashestos detect	Report ted by Polarised Light Microscop	In g of Results v (PLM) including Dispersion Staining (DS)
'No Asbestos Detected': No Asbestos 'UMF Detected': Mineral fibres of un	s detected by Polarised Light Micr known type detected by Polarise be necessary.	roscopy (PLM), including Dispersion Staining (DS)
independent analytical technique may l "Hand-picked" refers to small discrete a Limit of Detection & Reporting I Known limitations of the test procedure	amounts of asbestos unevenly distr Limit	ed Light Microscopy (PLM), including Dispersion Staining (DS). Confirmation by another ributed in a large body of non-asbestos material.
independent analytical technique may "Hand-picked" refers to small discrete a Limit of Detection & Reporting I Known limitations of the test procedure • PLM is a qualitative techni	amounts of asbestos unevenly distr Limit e using Polarised Light Microscop ique only:	ed Light Microscopy (PLM), including Dispersion Staining (DS). Confirmation by another ributed in a large body of non-asbestos material. vy (PLM) are:
independent analytical technique may l "Hand-picked" refers to small discrete a Limit of Detection & Reporting L Known limitations of the test procedure • PLM is a qualitative techni • It does not cover identifica • The less encountered ast identification by PLM and chrysotile ("white") and cro	amounts of asbestos unevenly distr Limit a using Polarised Light Microscop ique only: tion of airborne or water-borne asb- bestos mineral fibres actinolite, and Dispersion Staining (DS). Thus, to sidolite ("blue");	 d Light Microscopy (PLM), including Dispersion Staining (DS). Confirmation by another ributed in a large body of non-asbestos material. y (PLM) are: estos; thophyllite and tremolite exhibit a wide range of optical properties that preclude unequivocal the method is used to positively identify the three major asbestos minerals: amosite ("brown").
independent analytical technique may "Hand-picked" refers to small discrete a Limit of Detection & Reporting I Known limitations of the test procedure • PLM is a qualitative techni • It does not cover identifica • The less encountered ast identification by PLM and chrysotile ("white") and cro • Valid identification requires case, PLM and Dispersio Results relate only to the sample(s) sul test report must not be reproduced exe	amounts of asbestos unevenly distr Limit a using Polarised Light Microscop ique only: tition of airborne or water-borne asb- bestos mineral fibres actinolite, ant Dispersion Staining (DS). Thus, 1 ocidolite ("blue"); s that the sample material contains n Staining, which has a calculated bmitted for testing. cent in full	ed Light Microscopy (PLM), including Dispersion Staining (DS). Confirmation by another ributed in a large body of non-asbestos material. by (PLM) are: hestos; thophyllite and tremolite exhibit a wide range of optical properties that preclude unequivocal the method is used to positively identify the three major asbestos minerals: amosite ("brown"), a sufficient quantity of the unknown fibres in excess of the practical detection limit used (in this practical detection limit of 0.01-0.1% equivalent to 0.1-1g/kg (AS4946-2004:App. A4).

Sample No.	Client Ref.	Location	Physical Structure	Sample Description	Analysis of Fibrous Content
D1512	N/A	After school care – external window	Mastic	1gram	No Asbestos Detected
D1513	N/A	Preschool – external window	Mastic	1gram	No Asbestos Detected





Adam Dezman ACT Property Group PO Box 777 Fyshwick ACT 2609

05 February 2015

Dear Adam,

Re: Site assessment of previously identified asbestos containing materials located in the toilet at Yarralumla Preschool, Yarralumla ACT 2600 – 03 February 2015

Site Work

, Class A Asbestos Assessor of Robson Environmental sampled suspected asbestos containing material (ACM) from the above location. The assessment of the ACM is presented in Table 2. Photographs of material assessed are presented in Appendix A.

Risk Assessment

A Risk Assessment was undertaken on containing materials (ACM) to enable informed decisions to be made concerning the management of ACM as per *Code of Practice for the Management and Control of Asbestos in the Workplace.* This Risk Assessment takes into account:

- the type of ACM (non-friable or friable)
- the condition and location of the ACM
- whether the ACM is likely to be disturbed due to its condition and location and
- the likelihood of exposure to asbestos fibre

Material Assessment Restrictions and Caveats

Robson Environmental has taken care to ensure that this report includes the most accurate information available. This report does not constitute a full register of asbestos containing materials at the above establishment as required by State Legislation and the Code of Practice. The material assessments, recommendations and/or conclusions contained in this report must not be used to excuse a person of their responsibility to work in accordance with relevant Statutory Requirements, Codes of Practice, Guidelines, Material Safety Data Sheets, Work Instructions or reasonable work practices.

Table 1 details the ratings for the condition and associated risk of each positively identified asbestos material at the time of the assessment. The ratings for each item are presented in Table 2.



Table 1: ACM Condition & Risk Ratings

	ACM CONDITION RATING				
1	Severe	Material in very poor condition			
2	Poor	Deteriorated material and considerable damage			
3	Fair	Minor damage or signs of weathering			
4	4 Good Well sealed stable material				
	ACM RISK RATING				
Α	Very High	Exposure to airborne asbestos likely as a consequence of minor disturbance			
В	High	Exposure to airborne asbestos possible as a consequence of minor disturbance			
С	Medium	Exposure to airborne asbestos unlikely during normal building use			
D	Low	Negligible exposure to airborne asbestos during normal building use			

All inspections, sampling, identification and reporting was undertaken in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations.

Non-Friable ACM

Non-friable asbestos is any material that contains asbestos firmly bound into a matrix. It may consist of cement or various resins/binders and cannot be reduced to a dust by hand pressure. As such it does not present an exposure hazard unless cut, abraded, sanded or otherwise disturbed. Therefore, the exposure risk from non-friable ACM is negligible during normal building occupation.

Friable ACM

Friable asbestos material can be crumbled or reduced to a dust by hand pressure when dry. It can represent a significant exposure hazard as a consequence of minor disturbance. Examples of friable asbestos are hot water pipe lagging, severely damaged asbestos cement sheet, limpet spray to structural beams and electrical duct heater millboard.

Material Analysis & Assessment

Table 2: ACM Assessed

Location description	Material	Туре	Risk Rating	
Toilet walls	Sheet	Non Friable	3C	
Asbestos containing materia Presumed asbestos containi	l ng material			
Non- asbestos containing ma	aterial			

Conclusions & Recommendations

The ceramic wall tiles are loose on the right hand side wall and a few had fallen off the asbestos wall sheet and paint flakes observed on the floor. The toilet has been sealed to prevent access.

The short term remediation solution is to engage a licensed removalist to remove the ceramic tiles from all walls, environmentally clean the floor and encapsulate the walls with paint, which would allow reoccupation of the toilet. Longer term the walls should be removed during a preschool holiday period.

Asbestos Removal

Removal of ACM must be undertaken by a licensed Asbestos Removalist as per the *Code of Practice for the Safe Removal of Asbestos*. The removal/remediation of friable ACM must be undertaken by a licensed Class A Asbestos Removalist. Removal or remediation of non-friable asbestos may be undertaken by either an A or B Class Asbestos Removalist.

Prior to the commencement of any remediation/removal works associated with asbestos, a building certifier must be engaged and building approval sought. An application must also be submitted to WorkSafe ACT at least (5 days) prior to any friable or non-friable asbestos removal works commencing. An asbestos removal contractor must supply an Asbestos Removal Control Plan (ARCP) and a Safe Work Method Statement (SWMS). An independent licensed Class A Asbestos Assessor should be engaged to ensure that the ARCP addresses all safety issues relating to the planned asbestos works.

Air monitoring is mandatory during the removal or remediation of friable asbestos and should be considered during the removal or remediation of non-friable asbestos. Air sampling is to be undertaken in accordance with the *Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd* Edition and test certificates will be National Association of Testing Authorities (NATA) endorsed.

An independent Class A Asbestos Assessor must also be employed to undertake a Clearance Inspection of both friable and non-friable asbestos removal or remediation works. A satisfactory clearance certificate for the remediated areas must ensure that no visible asbestos or presumed asbestos remains. Additionally no asbestos fibres should be detected by laboratory analysis in any validation samples. All surfaces within the remediated area must be free of general dust and debris.



Material Analysis & Assessment

Yours sincerely,



LOCATION MATERIAL PHOTOGRAPH DESCRIPTION Toilet floor paint flakes Toilet wall where tiles Sheet have fallen off

APPENDIX A - PHOTOGRAPHS OF ASSESSED ACM





p. 02 6239 5656 f. 02 6239 5669 e. <u>admin@robsonenviro.com.au</u> Unit 1, 140 Gladstone Street Fyshwick ACT 2609 PO Box 112, Fyshwick ACT 2609 <u>www.robsonenviro.com.au</u> ABN 55 008 660 900

ASBESTOS CLEARANCE CERTIFICATE

Project/Location:	Yaralumla Pre School
Job Number:	7335-47-1
Date of Clearance:	Thursday, 26 February 2015
Description of Work:	Environmental clean in toilets

Asbestos Removalist:

Certification: Robson Environmental carried out background air monitoring and a visual inspection following the completion of the works listed above. It should be noted that this clearance certificate relates only to the exact areas specified above.

A visual inspection carried out on Thursday, 26 February 2015 by ACT Class A Asbestos Assessor, found no visible asbestos residue from the asbestos works in the area or in the vicinity of the area where the work was carried out. The work area has been given the "all clear" and restrictions associated with the asbestos removal can now be lifted and the area safely reoccupied.

Air monitoring was conducted at the sample locations indicated on the accompanying Respirable Fibre Estimation Test Report and yielded airborne fibre concentrations below the recommended Control Level of 0.01 fibres/mL as required by "Code of Practice For The Safe Removal Of Asbestos 2nd Edition [NOHSC:2002(2005)]".

Atmospheric measurements were carried out in accordance with the *Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC: 3003 (2005)]* and laboratory In-house Procedure No.1. Refer to the Respirable Fibre Estimation Test Report and the Explanatory Note on Interpreting the Clearance Certificate & Atmospheric Results.

Authorized by:

Robson Environmental Pty Ltd

Appendix 1. Air Monitoring Results





APPENDIX 1 - AIR MONITORING RESULTS

Keport No.: Monitoring Client Name Work in Pro Asbestos R Test Specifie	7335471 Sampling Date: 26 Location: Yaralumla Pre School & Address: ACT Property Group gress: Environmental clean i emovalist: Image: Complexity of the section of the se	Feb 2015 in toilets Note on t	the Me	Rej mbrane 1	Filter Me	thod for	Feb 2015 Estimatin
Airborne Ast	estos Fibres [NOHSC: 3003 (2005)], & In Sampling Location	-House Pro Tin On	ne Off	Av. Flowrate	No. of Fields Counted	No. of Fibres Counted	Airborne Fibre Conc. (fibres/mL
NO.							
7335471-4	On bookcase in centre of room	1615	1800	3000	100	1	<0.01
7335471-4 7335471-5	On bookcase in centre of room In kitchen area	1615 1620	1800 1801	3000 3000	100 100	1 2	<0.01 <0.01
7335471-4 7335471-5 7335471-6	On bookcase in centre of room In kitchen area In store room next to toilet	1615 1620 1622	1800 1801 1802	3000 3000 3000	100 100 100	1 2 1	<0.01 <0.01 <0.01
7335471-4 7335471-5 7335471-6 7335471-7	On bookcase in centre of room In kitchen area In store room next to toilet Field Blank	1615 1620 1622 -	1800 1801 1802 -	3000 3000 3000 -	100 100 100 100	1 2 1 0	<0.01 <0.01 <0.01

F	Robson Approved Signatory	NATA	Robson Approved Counter
		No. 3181	
	Accredited	d for compliance with ISO/IE	C 17025



ASBESTOS CLEARANCE INSPECTION PASS

Project/Location:	Yarralumla Primary School, Yarralumla ACT
Job Number:	7335471
Date of Inspection:	Wednesday, 25 March 2015
Description of Work:	Environmental clean and seal holes in asbestos eave sheet where a wire cover to light fitting had been damaged. See attached photograph.
Aspesius Nemuvalisi.	

Certification:

A visual inspection was carried out on Wednesday, 25 March 2015, by following the completion of the asbestos works listed above in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations. It should be noted that this clearance certificate relates only to the exact area specified above.

The inspection found no visible asbestos residue from the asbestos work in the area or in the vicinity of the area where the work was carried out.

The work area has been given the "all clear" and restrictions associated with the asbestos works can now be lifted and the area safely reoccupied.

Authorised by:

Appendix A – Photographs



Accredited for compliance with ISO/IEC 17020

Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ <u>admin@robsonenviro.com.au</u> PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609



7335471_Yarralumla Primary_Pass_Clear_Cert_20150325



APPENDIX A - PHOTOGRAPHS



Photograph 1: Environmental clean and seal holes in asbestos eave sheet where a wire cover to light fitting had been damaged.

Client:

From:Connors, KevinTo:Ebner, JoanneSubject:FW: Yarraluma Primary Gamberi buildingDate:Monday, 30 March 2015 10:45:01 AMAttachments:Image: Constant State

Hi Jo

As discussed, confirmation from Robson's re proposal for Eaves at Yarralumla.

Regards

KEVIN CONNORS | PROJECT MANAGER | PROPERTY PROJECTS AND SERVICES | ACT PROPERTY GROUP | CHIEF MINISTERS, TREASURY & ECONOMIC DEVELOPMENT DIRECTORATE | ACT GOVERNMENT | P: 02 62059504| F: +61 2 621 30735 | M: 0466 305 154 | E: <u>kevin.connors@act.gov.au</u>

From: Sent: Monday, 30 March 2015 10:34 AM To: Connors, Kevin Cc: Subject: Yarraluma Primary Gamberi building

Hi Kevin,

As discussed earlier, the eaves can be repainted at the Gamberi building, Yarraluma Primary school so long as an asbestos removalist conducts all the preparation work e.g. remove any loose flaking paint. Under no circumstances should the eaves be dry sanded or water blasted.

Regards

?	
Web: www.robsonenviro.com.au	



ASBESTOS CLEARANCE INSPECTION PASS

Project/Location:	Yarralumla Primary School, Loftus Street, Yarralumla, ACT
Job Number:	7335471
Client:	ACT Property Group
Client Contact:	Adam Dezman –
Time And Date Of Inspection:	1300 Saturday, 13 February 2016
Date(s) And Description Of Work:	Environmental clean and removal of friable asbestos pipe lagging residue to pipe flanges, pipe brackets and walls in the boiler room.

Asbestos Removalist:

Certification:

A visual inspection was carried out on Saturday, 13 February 2016, by following the completion of the asbestos works listed above in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations. It should be noted that this clearance certificate relates only to the exact area(s) specified above.

The inspection found no visible asbestos residue from the asbestos work in the area or in the vicinity of the area where the work was carried out.

Air monitoring during the works returned results below the minimum practical detection limit of <0.01 F/mL.

The work area has been given the "all clear" and restrictions associated with the asbestos works can now be lifted and the area safely reoccupied.

Authorised by:



Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ <u>admin@robsonenviro.com.au</u> PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609



Appendix A – Air Monitoring Results



Fibre Estimation Respirable Repor Test

Report No.: 7335471 **Monitoring Location:** Work in Progress:

Report Issued: 13/02/2016 Sampling Date: 13/02/2016 Yarralumla Primary School, Loftus Street, Yarralumla, ACT 2600 Client Name & Address: ACT Property Group 255 Canberra Avenue Fyshwick ACT 2609 Environmental clean and removal of friable asbestos pipe lagging residue to pipe flanges, pipe brackets and walls in the boiler room.

Asbestos Removalist:

Test Specifications(s) Employed: NOHSC: Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres [NOHSC: 3003 (2005)], In-House Procedure No. 1

Sample No.		Time		Av.	Fields	Fibres	Fibre
	Sample Location	On	Off	Flow Rate	Counted	Counted	(fibres/mL)
7335471-008	On decon unit -	07:50	14:33	1000	100	0	< 0.01
7335471-009	On plastic barrier to removal area east -	07:53	14:34	1000	100	0	< 0.01
7335471-010	On temporary fence adjacent to window north of removal area -	07:55	14:36	1000	100	0	< 0.01
7335471-011	On temporary fence adjacent to window south of removal area -	07:57	14:37	1000	100	0	< 0.01
7335471-012	Clearance inside boiler room removal area - Clearance: Pass	13:00	14:40	4000	100	1	< 0.01
7335471-013 eld blanks and sar	Field Blank	- inits are re	- ported as a	- fibre count o	100	0	÷
7335471-013 eld blanks and sar DR = Filter too he he Detection Limi he Work Health au /orksafe Australia	Field Blank mples taken in direct flow of negative air u avily loaded with background dust to r t of the analytical method is 0.01 fibres nd Safety Act 2011 Control Level for all 's recommended Exposure Standard for	- ead s/mL forms of a or all form	- ported as a asbestos i s of asbes	- fibre count o s 0.01 fibres/ tos is 0.1 fib	100 nly mL res/mL	0	
7335471-013 eld blanks and sar DR = Filter too he he Detection Limi he Work Health an 'orksafe Australia Robson A	Field Blank mples taken in direct flow of negative air u avily loaded with background dust to r t of the analytical method is 0.01 fibres nd Safety Act 2011 Control Level for all r's recommended Exposure Standard for pproved Signatory	- ead s/mL forms of a for all form	asbestos i s of asbes	- s 0.01 fibres/ tos is 0.1 fib	100 nly /mL res/mL Robson Ap	0 pproved Cou	Inter
7335471-013 eld blanks and sar DR = Filter too he ne Detection Limi orksafe Australia Robson A	Field Blank mples taken in direct flow of negative air u avily loaded with background dust to r t of the analytical method is 0.01 fibres ind Safety Act 2011 Control Level for all 's recommended Exposure Standard f pproved Signatory Accredited for co	- inits are relead i/mL forms of i or all form No. 3181	ported as a asbestos i s of asbes	- s 0.01 fibres/ tos is 0.1 fib	100 nly mL res/mL Robson Ap	0 pproved Cou	Inter

PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609

Page 1 of 1



Appendix B – Photographs



Photograph 1: Environmental clean and removal of friable asbestos pipe lagging residue to pipe flanges, pipe brackets and walls in the boiler room.



Photograph 2: Environmental clean and removal of friable asbestos pipe lagging residue to pipe flanges, pipe brackets and walls in the boiler room.



Photograph 3: Environmental clean and removal of friable asbestos pipe lagging residue to pipe flanges, pipe brackets and walls in the boiler room.



Photograph 4: Environmental clean and removal of friable asbestos pipe lagging residue to pipe flanges, pipe brackets and walls in the boiler room.



ASBESTOS CLEARANCE INSPECTION PASS

Project/Location:	Yarralumla Primary School, Loftus Street, Yarralumla, ACT
Job Number:	7335471
Client:	ACT Property Group
Client Contact:	Adam Dezman –
Time And Date Of Inspection:	12.00pm Sunday, 14 February 2016
Date(s) And Description Of Work:	Removal of non friable asbestos ceiling sheets to flue in the boiler room.

Asbestos Removalist:

Certification:

A visual inspection was carried out on Sunday, 14 February 2016, by following the completion of the asbestos works listed above in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations. It should be noted that this clearance certificate relates only to the exact area(s) specified above.

The inspection found no visible asbestos residue from the asbestos work in the area or in the vicinity of the area where the work was carried out.

Air monitoring during the works returned results below the minimum practical detection limit of <0.01 F/mL.

The work area has been given the "all clear" and restrictions associated with the asbestos works can now be lifted and the area safely reoccupied.

Note: this was a partial removal of damaged ceiling sheets around the flue on the right hand side. Asbestos ceiling sheets still remain around the flue on the left hand side. The edges to the remaining ceiling sheets have been sprayed with paint to prevent any fibre release. Care should be taken when working around the asbestos ceiling sheets.

Authorised by:



Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ <u>admin@robsonenviro.com.au</u> PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609





Appendix A – Air Monitoring Results



Respirable Fibre Estimation Test Repo

Report No.: 7335471 **Monitoring Location:** Work in Progress:

Report Issued: 14/02/2016 Sampling Date: 14/02/2016 Yarralumla Primary School, Loftus Street, Yarralumla, ACT 2600 Client Name & Address: ACT Property Group 255 Canberra Avenue Fyshwick ACT 2609 Removal of non friable asbestos ceiling sheets around flue in the boiler room.

Asbestos Removalist:

Test Specifications(s) Employed: NOHSC: Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres [NOHSC: 3003 (2005)], In-House Procedure No. 1

Sample No.		Time			No. of Fields	No. of Fibres	Airborne Fibre
	Sample Location	On	Off	Av. Flow Rate	Counted	Counted	Conc. (fibres/mL)
7335471-014	Adjacent entry to removal area -	08:00	12:02	2000	100	1	< 0.01
7335471-015	On temp fence adjacent window to removal area north -	08:02	12:04	2000	100	3	< 0.01
7335471-016	On temp fence adjacent removal area south -	08:04	12:07	2000	100	0	< 0.01
7335471-017	Field Blank		-		100	0	

Field blanks and samples taken in direct flow of negative air units are reported as a fibre count only TDR = Filter too heavily loaded with background dust to read

The Detection Limit of the analytical method is 0.01 fibres/mL The Work Health and Safety Act 2011 Control Level for all forms of asbestos is 0.01 fibres/mL Worksafe Australia's recommended Exposure Standard for all forms of asbestos is 0.1 fibres/mL



Robson Approved Counter

Accredited for compliance with ISO/IEC 17025

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards

Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ admin@robsonenviro.com.au PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609

Robson Approved Signatory



Page 1 of 1



Appendix B – Photographs



Photograph 1: Removal of non friable asbestos ceiling sheets to flue in the boiler room.



Photograph 2: Remaining of non friable asbestos ceiling sheets to flue on the left hand side.



ASBESTOS CLEARANCE INSPECTION PASS

Project/Location:	Yarralumla Primary School, Loftus St, Yarralumla ACT

Client: ACT Property Group

Client Contact: Adam Dezman –

Time And Date Of Inspection:12:00pm Saturday, 17 September 2016

Date(s) And Description Of Work: Removal of 4x non friable asbestos eave sheets adjacent to the pergola at the pre area

Asbestos Removalist:

Certification:

A visual inspection was carried out on Saturday, 17 September 2016, by following the completion of the asbestos works listed above in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations. It should be noted that this clearance certificate relates only to the exact area(s) specified above.

The inspection found no visible asbestos residue from the asbestos work in the area or in the vicinity of the area where the work was carried out.

Air monitoring during the works returned results below the minimum practical detection limit of <0.01 F/mL.

The work area has been given the "all clear" and restrictions associated with the asbestos works can now be lifted and the area safely reoccupied.

Note: This was only a partial removal to allow works to proceed. Asbestos containing eaves still remain in situ and must not be disturbed.

Authorised by:



Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ <u>admin@robsonenviro.com.au</u> PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609





Appendix A – Air Monitoring Results

Report No: 7335471-160917-01



Respirable Fibre Estimation e s t Report

Job No.: 7335471 **Monitoring Location:** Work in Progress:

Sampling Date: 17/09/2016 Report Issued: 17/09/2016 Yarralumla Primary School, Loftus Street, Yarralumla, ACT 2600 Client Name & Address: ACT Property Group 255 Canberra Avenue Fyshwick ACT 2609 Removal of 4x non friable asbestos eaves adjacent to the pergola at the pre area

Asbestos Removalist:

Test Specifications(s) Employed: NOHSC: Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres [NOHSC: 3003 (2005)], In-House Procedure No. 1

Sample No.		Time			No. of Fields	No. of Fibres	Airborne Fibre
	Sample Location	On	Off	Flow Rate	Counted	Counted	Conc. (fibres/mL)
7335471-018	On rear wall adjacent removal area adjacent tap -	10:00	12:01	3000	100	0	< 0.01
7335471-019	On water tank adjacent removal area -	10:02	12:02	3000	100	0	< 0.01
7335471-020	On side wall adjacent removal area -	10:04	12:03	3000	100	0	< 0.01
7335471-021	Field Blank		÷.		100	0	-

Field blanks and samples taken in direct flow of negative air units are reported as a fibre count only TDR = Filter too heavily loaded with background dust to read

The Detection Limit of the analytical method is 0.01 fibres/mL The Work Health and Safety Act 2011 Control Level for all forms of asbestos is 0.01 fibres/mL

Worksafe Australia's recommended Exposure Standard for all forms of asbestos is 0.1 fibres/mL



Robson Approved Counter

Robson Approved Signatory

Accredited for compliance with ISO/IEC 17025

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards

Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ admin@robsonenviro.com.au PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609

Page 1 of 1





Appendix B – Photo(s)





Appendix C - Site Plan



Robson Environmental Pty Ltd ~ ABN: 55 008 660 900 ~ www.robsonenviro.com.au p: 02 6239 5656 ~ f: 02 6239 5669 ~ admin@robsonenviro.com.au PO Box 112 Fyshwick ACT 2609 ~ 140 Gladstone Street Fyshwick ACT 2609



Client: ACT PG